

Figure 1. Service Road to easement




Figure 2. Service Road along easement



Figure 3. Partially cleared vegetation



Figure 4. Cleared vegetation



Figure 6. Sept 05. View SW from base Camp.




Figure 7. Sept 05. Pond 1 from SE corner of pond near easement.



Figure 8. Sept 05. Construction of Drain/Intake for Pond 1 on creek side.



Figure 9. Sept 05. Re-enforcement Pond 2 dikes.



Figure 10. Sept 05. Pond 3



Figure 11. Sept 05. Pond 4



Figure 12. Sept 05. Pond 3



Figure 13. Sept 05. Pond 3



Figure 14. Oct 05. SW view from Pond 1



Figure 15. Oct 05. Settlement pond 1



Figure 16. Oct 05. Second power pole with a junction box between settlement ponds 1 and 2.

